

# NOTICE TO MARINERS

## No. 17 – 2017

### Discontinuation of Obsolete Navigation Marks

NOTICE IS HEREBY GIVEN that it is proposed to request Trinity House to formally delete from their records the following obsolete or missing navigation marks –

| AtoN No | Aid To Navigation                    | Location                   | Description      |
|---------|--------------------------------------|----------------------------|------------------|
| N18121  | B – Aylesford - Cables/Pipes Warning | Near Aylesford Road Bridge | Notice-Board     |
| N18120  | A - New Hythe - Cable/Pipes Warning  | Near Lower Cut Beacon      | Notice-Board     |
| N05565  | Burham Water Main Crossing E         |                            | Unlighted Beacon |
| N05566  | Burham Water Main Crossing W         |                            | Unlighted Beacon |
| N05557  | Snodland Gas Pipeline West           |                            | Unlighted Beacon |
| N05554  | Halling Water Main Crossing W        |                            | Unlighted Beacon |
| N05553  | Halling Water Main Crossing E        |                            | Unlighted Beacon |
| N17376  | Halling Marshes Sewer South Bank     |                            | Unlighted Beacon |
| N17377  | Halling Marshes Sewer North Bank     |                            | Unlighted Beacon |
| N17377  | Halling Marshes Sewer North Bank     |                            | Unlighted Beacon |
| N10542  | Cuxton Cable Crossing W              |                            | Unlighted Beacon |
| N05505  | Chatham Reach Cable W. Bank          |                            | Unlighted Beacon |
| N08945  | Close to St. Marys Wharf Pontoon     |                            | Unlighted Beacon |
| N05483  | Gillingham Marina Wall               |                            | Unlighted Beacon |
| N05480  | Gillingham Strand Sewage Outfall     | Outer                      | Unlighted Beacon |
| N05473  | No.3 Beacon                          |                            | Unlighted Beacon |
| N17375  | Motney Hill Sewer Crossing           | Otterham Creek             | Unlighted Beacon |
| N13381  | Sittingbourne Outfall North Bank     | Milton Creek               | Unlighted Beacon |
| N13382  | Sittingbourne Outfall South Bank     | Milton Creek               | Unlighted Beacon |
| N10536  | Faversham Creek Outfall              |                            | Unlighted Beacon |

**In addition, the following marks are proposed to be re-classified -**

|        |                                   |  |
|--------|-----------------------------------|--|
| N05570 | Island Site Footbridge Upstream   | Lighted Beacon - Re-classify light as FR |
| N05569 | Island Site Footbridge Downstream | Lighted Beacon - Re-classify light as FR |
|        | Mid Cant Beacon                   | Lighted Beacon – Re-classify as ‘Ruin’   |

Any party that has any comments or questions regarding this notice are requested to contact Peel Ports Medway at the address below by 30<sup>th</sup> June 2017.

Captain Ian Clark AFRIN AFNI  
Manager Marine Operations

30<sup>th</sup> May 2017

**Port of Sheerness Limited**  
Sheerness Docks  
Sheerness  
Kent  
ME12 1RS

T: +44 (0)1795 596 596  
F: +44 (0)1795 660 072  
E: [info@peelports.co.uk](mailto:info@peelports.co.uk)  
W: [www.peelports.co.uk](http://www.peelports.co.uk)

